

Special Process: Plating System Assessment			
Facility Name:		Galfa GmbH & Co KG	
Address: Pflaumenalle 4, 03238 Finsterwalde			
Phone Number:	+49353165040	<b>Type(s) of Plating Processing at this Facility:</b>	
Fax Number:	+493531650416	<b>Process Table A</b>	
Number of Plating Employees at this Facility:195		Zinc	X
		Zinc Alloy Plating	X
Captive Plater (Y/N):	Y	<b>Process Table B</b>	
Commercial Plater (Y/N):	Y	Surface Conditioning of Metals for Decorative Plating	
Date of Assessment:		<b>Process Table C</b>	
8-Mar-2019		Surface Conditioning of ABS & PCABS Plastics for Decorative Plating	
Date of Previous Assessment:		<b>Process Table D</b>	
6-Mar-2018		Decorative Plating	
		<b>Process Table E</b>	
		Mechanical Plating	
		<b>Process Table F</b>	
		Equipment	
		Process Equipment	
Current Quality Certification(s):		IATF 16949, ISO 14001, ISO 9001	
Date of Re-assessment (if necessary):			
<b>Personnel Contacted:</b>			
<b>Name:</b>	<b>Title:</b>	<b>Phone:</b>	<b>Email:</b>
Norbert Lewan	Head of Technology & Quality	+493531650460	<a href="mailto:nlewan@galfa.de">nlewan@galfa.de</a>
Daniel Hellmuth	Sales	+493531650418	<a href="mailto:dhellmuth@galfa.de">dhellmuth@galfa.de</a>
<b>Auditors/Assessors:</b>			
<b>Name:</b>	<b>Company:</b>	<b>Phone:</b>	<b>Email:</b>
Daniela Kaiser	Galfa GmbH & Co KG	+493531650448	<a href="mailto:dkaiser@galfa.de">dkaiser@galfa.de</a>
<b>Number of "Not Satisfactory" Findings:</b>			
0			
<b>Number of "Needs Immediate Action" Findings:</b>			
0			
<b>Number of "Fail" Findings in the Job Audit(s):</b>			
0			